

Service Bulletin No.: 06 29-11-2004

Priority: Red Alert

All Marinfloc Equipment* Using General Service Air

Since some, even if a very small number, pneumatic operated valves have jammed/seized because of a high concentration of impurities in the actual ship(s) General Service Air System, we do recommend all owners of subject Marinfloc Equipment*, to install a combined Water Trap - Air Filter.

The Equipment* concerned is:

- Emulsion Breaking Bilge Water Cleaning System (EBBWCS) Mk I and Mk II models. All types.
- Sludge De watering Unit (SDwU).All types
- White Box System (WBS). All types
- Emulsion Breaking Pre Treatment (EB Pre-T) All types

Note!

All our EBBWCS Mk III CD models and of all types have from start of production been equipped with a Water Trap – Air Filter

Further:

All other equipment concerned, which will be delivered from our production plants after December 1st 2004, will also be equipped with a Water Trap - Air Filter.

Since the quality of the General Service Air Supply obviously does vary from ship to ship, the arrangements above will still allow us in just having one common Air Supply to all pneumatic functions and air consumers at the same Marinfloc System/Unit(s).

Marinfloc AB 29 11 2004